
FIG. 1





Darryl Mexic (202) 293-7060 2 of 9

2/9

FIG. 2

<u>4</u>







FIG. 3








FIG. 4

17






FIG. 5






FIG. 6



NORMALIZED EFFECTIVE RADIUS


ABERRATION DISTRIBUTION OF THE LIGHT BEAM BEFORE CORRECTION

FIG. 7



50,604 Q68036 RATION CORRECTION APPARATUS Darryl Mexic (202) 293-7060 7 of 9

FIG. 8



DIBLITION OF BLASE DIFFERENCE

DISTRIBUTION OF PHASE DIFFERENCE PROVIDED BY LIQUID CRYSTAL

FIG. 9





FIG. 10



ERROR OF COVER LAYER THICKNESS ($\mu\,\mathrm{m}$)



9/9

FIG. 11

